

City of San Diego
FY15 Facility Condition Assessment Report for:
Facility # 000008 Office. City Operations Building. COB. Downtown

FACILITY EXECUTIVE SUMMARY



| Facility Statistics | |
|---------------------------------------|----------------------|
| Council District | 3 |
| Community Group | Downtown |
| Year Built | 1970 |
| Gross Square Feet | 217,669 |
| Address | 1222 1st. Avenue |
| Latitude | 32.71816 |
| Longitude | -117.163974 |
| Building Value | \$169,433,550 |
| Site Value | \$3,310,745 |
| Plant Replacement Value (PRV) | \$172,744,295 |
| Facility Condition and Backlog | |
| Condition Rating | Poor |
| Facility Condition Index (FCI) | 75 |
| Building | \$82,396 |
| Site | \$0 |
| Total Maintenance Backlog* | \$82,396 |
| Building | \$125,102,753 |
| Site | \$3,671,423 |
| Total Capital Backlog* | \$128,774,176 |
| Building | \$125,185,148 |
| Site | \$3,671,423 |
| Total Backlog* | \$128,856,571 |

* See next page for definitions of terminology. It is not agency Best Management Practice to improve existing facilities to a \$0 backlog. Adopting an appropriate Service Level establishes the acceptable FCI, Condition Rating, and Backlog for the facility. Backlog values do not include future needs, capital renewal, improvements, expansion, or upgrades. This static report is based on FY15 data and estimates. The facility's current condition may differ due to subsystem deterioration and work completed at the facility. The data in this report was used to prepare FY16 City Council Item 330 docketed on March 14, 2017.

FY16 Proposed Service Level: **FCI 20 - Good Condition Rating**
FY16 Proposed Reinvestment Amount: **\$94,307,712**

Please refer to the following sections within this report for further details:

| | |
|----------------------------|---|
| Glossary | Definitions of terminology |
| Cost Model Report | Subsystem Lifecycle and Replacement Costs |
| Forecast Report | Backlog and 20 year capital renewal forecast by Subsystem |
| Deficiency Report | Prioritized list of current and future maintenance repairs and capital replacements |
| Equipment Inventory | Details for equipment installed as part of a subsystem, ex. HVAC units |
| Solar Assessment | Solar system feasibility analysis (energy use, installation issues) and pre-design |

Note: This report includes a set of reports for the assets in or on the building marked " **building only**" and a sequential set of reports for the site around the building marked " **site only**". Values shown in report have been extracted from a database and rounded to whole numbers which may introduce minor variances.

DEFINITIONS for FACILITY EXECUTIVE SUMMARY

Facility # 000008 Office. City Operations Building. COB. Downtown

Backlog: The cost to correct maintenance or life cycle subsystem deficiencies. Backlog costs do not include future needs, capital renewal, improvements, expansion, or upgrades.

Total Backlog is the sum of the **Capital Backlog** and **Maintenance Backlog**.

Capital Backlog: The cost to replace subsystems that are in service past the end of their life cycle and will eventually fail if not replaced. (Cost to replace HVAC, roof, doors, windows, etc.)

Maintenance Backlog: The cost to correct deficiencies that are related to maintaining or repairing a facility subsystem (eg. Repairing foundation cracks, sealing concrete, repairing roof leaks, replacing a corroded coil in an HVAC unit).

Capital Renewal: The cost to replace a subsystems that will reach the end of its life cycle in future years according to the anticipated life cycle.

Condition Rating: The state of physical fitness or service readiness of a facility based on the subsystems that make up the facility (subsystems include foundation, walls, roof, mechanical, electrical, etc.). The Condition Rating for the facility is determined by the FCI score for the facility as follows:

| FCI Score Range | Corresponding Condition Rating |
|-----------------|--------------------------------|
| 0 to 20 | Good |
| 21 to 29 | Fair |
| 30 and greater | Poor |

Facility Condition Index (FCI): An industry-standard condition score for a facility that is calculated as follows:

$$\frac{\text{Total Backlog}}{\text{Plant Replacement Value (PRV)}}$$

Gross Square Feet (GSF): The enclosed floor area in a building or under a structure measured to the outside of the structure.

Life Cycle: The period of time that a building, system or element can be expected to adequately serve its intended function. The anticipated Life Cycle for each facility subsystem is included in the Cost Model Report.

Plant Replacement Value (PRV): The cost to rebuild the same facility at the same location. The PRV is the sum of the **Building Value** and the **Site Value**.

Building Value: The cost to rebuild the building including the systems in or on the building not including operational assets that are not inherent to the building (eg. Water pumps in a water treatment plant, computers in an office).

Site Value: The cost to rebuild the systems outside the building such as parking lots, fencing, lighting, landscaping, etc.

Proposed Reinvestment Amount: The cost to improve the condition of a facility from its current FCI to the Service Level FCI. If the current FCI is less than the Service Level FCI, the Proposed Reinvestment Amount is \$0. The Proposed Reinvestment Amount is calculated as follows:

$$\frac{(\text{FCI} - \text{Service Level FCI}) * \text{PRV}}{100}$$

Service Level: FCI and Condition Rating goals that are established for existing facilities throughout their life cycle to ensure service readiness.

COST MODEL REPORT: Summary of existing Subsystem values and Life Cycle information. Cost Model data does not include operational or community needs such as upgrades, improvements, expansions or building replacements.

DEFINITIONS for COST MODEL REPORT (in order presented in spreadsheet):

Subsystem: Building and Site assets that are inherent to the building operation such as HVAC provides heating, ventilating, and air conditioning and electrical systems provide power to the building.

Priority: The relative importance of correcting the deficiency (ie replacing the subsystem or performing maintenance repairs). The priority levels used in this condition assessment are Critical, Potentially Critical, Necessary, Recommended, and Not Applicable.

Cost per Square Foot: Cost per square foot of building area to replace a subsystem including hard costs (direct construction costs such as labor, materials, and equipment).

Total Cost per Square Foot: Cost per square foot of building area to replace a subsystem including hard costs and soft costs (indirect costs such as professional services, financing, taxes, etc.)

Gross Square Feet (GSF): The enclosed floor area in a building or under a structure measured to the outside of the structure.

Replacement Cost in New Facility: Cost to replace a subsystem as part of replacing the entire facility with a new facility including hard costs and soft costs.

Percent Renewed: An additional replacement cost that applies to stand-alone projects in existing buildings which accounts for disruption and repair of nearby subsystems. Example: when replacing a roof covering, work is also required on hvac units, electrical, plumbing, rainwater drains, etc.

Replacement Cost for Stand-Alone Projects: Cost to replace a subsystem as a stand-alone project in an existing facility.

Last Renovation Year: The year the subsystem was replaced or the original installation year if not renovated.

Life Cycle: The period of time that a building, system or element can be expected to adequately serve its intended function. Life Cycles for each subsystem are adopted from Building Owners and Managers Association (BOMA) International publication "How to Design and Manage Your Preventive Maintenance Program" Copyright 1996.

Override Default Renewal Year: The year that the subsystem will reach the end of its life cycle as overridden by the assessor. This override is used by the assessor in cases where the subsystem is anticipated to operate shorter or longer than its life cycle.

Next Renewal Year: The year that the subsystem will reach the end of its life cycle. Calculated by adding the Life Cycle to the Last Renovation Year.

Backlog: The cost to correct maintenance or life cycle subsystem deficiencies. Backlog costs do not include future needs, capital renewal, improvements, expansion, or upgrades.

Capital Renewal: The cost to replace a subsystem that will reach the end of its life cycle in future years according to the anticipated life cycle.

Facility # 000008 Office. City Operations Building. COB. Downtown

| COST MODEL REPORT – Building Only | | | | | | | | | | | | | |
|-----------------------------------|----------------------|----------------------|----------------------------|-------------------|--|-----------------|---|----------------|------------|-------------------------------|-------------------|------------------|-----------------|
| Subsystem | Priority | Cost Per Square Foot | Total Cost Per Square Foot | Gross Square Feet | Replacement Cost in New Facility (Plant Replacement Value) | Percent Renewed | Replacement Cost for Stand-Alone projects | Last Reno Year | Life Cycle | Override Default Renewal Year | Next Renewal Year | Backlog | Capital Renewal |
| Totals | | \$518.92 | \$778.40 | 217,669 | \$169,433,549.60 | | \$245,643,275.71 | | | | | \$125,185,148.41 | \$50,291,917.90 |
| Standard Foundations | Potentially Critical | \$5.18 | \$7.77 | 217,669 | \$1,691,288.13 | 145 | \$2,452,367.79 | 1970 | 100 | 0 | 2070 | \$0.00 | \$0.00 |
| Special Foundations | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Slab on Grade | Potentially Critical | \$2.20 | \$3.30 | 217,669 | \$718,307.70 | 145 | \$1,041,546.16 | 1970 | 100 | 0 | 2070 | \$0.00 | \$0.00 |
| Basement Excavation | Potentially Critical | \$0.25 | \$0.38 | 217,669 | \$82,714.22 | 145 | \$119,935.62 | 1970 | 100 | 0 | 2070 | \$0.00 | \$0.00 |
| Basement Walls | Potentially Critical | \$6.96 | \$10.44 | 217,669 | \$2,272,464.36 | 145 | \$3,295,073.32 | 1970 | 100 | 0 | 2070 | \$0.00 | \$0.00 |
| Floor Construction | Potentially Critical | \$49.98 | \$74.97 | 217,669 | \$16,318,644.93 | 145 | \$23,662,035.15 | 1970 | 100 | 0 | 2070 | \$0.00 | \$0.00 |
| Roof Construction | Potentially Critical | \$9.39 | \$14.08 | 217,669 | \$3,064,779.52 | 145 | \$4,443,930.30 | 1970 | 100 | 0 | 2070 | \$0.00 | \$0.00 |
| Exterior Walls | Potentially Critical | \$68.14 | \$102.21 | 217,669 | \$22,247,948.49 | 145 | \$32,259,525.31 | 1970 | 100 | 0 | 2070 | \$0.00 | \$0.00 |
| Exterior Windows | Necessary | \$16.85 | \$25.28 | 217,669 | \$5,502,672.32 | 150 | \$8,254,008.48 | 1970 | 40 | 0 | 2010 | \$8,254,008.48 | \$0.00 |
| Exterior Doors | Necessary | \$4.28 | \$6.42 | 217,669 | \$1,397,434.98 | 150 | \$2,096,152.47 | 1970 | 40 | 0 | 2010 | \$2,029,471.76 | \$0.00 |
| Roof Coverings | Critical | \$2.19 | \$3.28 | 217,669 | \$713,954.32 | 165 | \$1,178,024.63 | 1995 | 20 | 0 | 2015 | \$1,178,024.63 | \$0.00 |
| Partitions | Recommended | \$15.57 | \$23.36 | 217,669 | \$5,084,747.84 | 155 | \$7,881,359.15 | 1970 | 75 | 0 | 2045 | \$0.00 | \$0.00 |
| Interior Doors | Recommended | \$24.60 | \$36.90 | 217,669 | \$8,031,986.10 | 150 | \$12,047,979.15 | 1970 | 30 | 0 | 2000 | \$12,047,979.15 | \$0.00 |
| Fittings | Recommended | \$4.28 | \$6.42 | 217,669 | \$1,397,434.98 | 150 | \$2,096,152.47 | 2007 | 30 | 0 | 2037 | \$0.00 | \$0.00 |
| Stair Construction | Potentially Critical | \$19.78 | \$29.67 | 217,669 | \$6,458,239.23 | 150 | \$9,687,358.84 | 1970 | 75 | 0 | 2045 | \$0.00 | \$0.00 |
| Stair Finishes | Recommended | \$1.98 | \$2.97 | 217,669 | \$646,476.93 | 145 | \$937,391.55 | 1970 | 20 | 0 | 1990 | \$937,391.55 | \$0.00 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| COST MODEL REPORT – Building Only | | | | | | | | | | | | | |
|-----------------------------------|----------------------|----------------------|----------------------------|-------------------|--|-----------------|---|----------------|------------|-------------------------------|-------------------|-----------------|-----------------|
| Subsystem | Priority | Cost Per Square Foot | Total Cost Per Square Foot | Gross Square Feet | Replacement Cost in New Facility (Plant Replacement Value) | Percent Renewed | Replacement Cost for Stand-Alone projects | Last Reno Year | Life Cycle | Override Default Renewal Year | Next Renewal Year | Backlog | Capital Renewal |
| Wall Finishes | Recommended | \$4.90 | \$7.35 | 217,669 | \$1,599,867.15 | 145 | \$2,319,807.37 | 1970 | 10 | 0 | 1980 | \$2,319,807.37 | \$0.00 |
| Floor Finishes | Recommended | \$34.32 | \$51.48 | 217,669 | \$11,205,600.12 | 145 | \$16,248,120.17 | 1970 | 10 | 0 | 1980 | \$16,248,120.17 | \$0.00 |
| Ceiling Finishes | Recommended | \$28.81 | \$43.22 | 217,669 | \$9,407,654.18 | 145 | \$13,641,098.56 | 1970 | 25 | 0 | 1995 | \$13,641,098.56 | \$0.00 |
| Elevators and Lifts | Necessary | \$51.75 | \$77.62 | 217,669 | \$16,895,467.78 | 135 | \$22,808,881.50 | 1970 | 30 | 0 | 2000 | \$21,440,921.30 | \$1,585,876.26 |
| Escalators and Moving Walks | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Other Conveying Systems | Necessary | \$0.89 | \$1.34 | 217,669 | \$291,676.46 | 145 | \$422,930.87 | 1970 | 30 | 0 | 2000 | \$422,930.87 | \$0.00 |
| Plumbing Fixtures | Necessary | \$15.24 | \$22.86 | 217,669 | \$4,975,913.34 | 135 | \$6,717,483.01 | 1970 | 30 | 0 | 2000 | \$6,717,483.01 | \$0.00 |
| Domestic Water Distribution | Potentially Critical | \$1.81 | \$2.72 | 217,669 | \$592,059.68 | 145 | \$858,486.54 | 1970 | 30 | 0 | 2000 | \$858,486.54 | \$0.00 |
| Sanitary Waste | Recommended | \$2.71 | \$4.06 | 217,669 | \$883,736.14 | 150 | \$1,325,604.21 | 1970 | 30 | 0 | 2000 | \$1,325,604.21 | \$0.00 |
| Rain Water Drainage | Necessary | \$2.55 | \$3.82 | 217,669 | \$831,495.58 | 145 | \$1,205,668.59 | 1970 | 30 | 0 | 2000 | \$1,205,668.59 | \$0.00 |
| Other Plumbing Systems | Recommended | \$0.12 | \$0.18 | 217,669 | \$39,180.42 | 145 | \$56,811.61 | 2000 | 20 | 0 | 2020 | \$0.00 | \$65,861.70 |
| Energy Supply | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Heat Generating Systems | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 1970 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Cooling Generating Systems | Potentially Critical | \$0.60 | \$0.90 | 217,669 | \$195,902.10 | 145 | \$284,058.04 | 1970 | 30 | 0 | 2000 | \$122,598.37 | \$244,223.90 |
| Distribution Systems | Necessary | \$36.90 | \$55.35 | 217,669 | \$12,047,979.15 | 145 | \$17,469,569.77 | 1970 | 30 | 0 | 2000 | \$17,279,895.31 | \$268,623.25 |
| Terminal and Package Units | Potentially Critical | \$1.29 | \$1.94 | 217,669 | \$422,277.86 | 145 | \$612,302.90 | 2000 | 20 | 0 | 2020 | \$4,447.93 | \$704,084.91 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| COST MODEL REPORT – Building Only | | | | | | | | | | | | | |
|-----------------------------------|----------------------|----------------------|----------------------------|-------------------|--|-----------------|---|----------------|------------|-------------------------------|-------------------|----------------|-----------------|
| Subsystem | Priority | Cost Per Square Foot | Total Cost Per Square Foot | Gross Square Feet | Replacement Cost in New Facility (Plant Replacement Value) | Percent Renewed | Replacement Cost for Stand-Alone projects | Last Reno Year | Life Cycle | Override Default Renewal Year | Next Renewal Year | Backlog | Capital Renewal |
| Controls and Instrumentation | Necessary | \$3.99 | \$5.98 | 217,669 | \$1,301,660.62 | 145 | \$1,887,407.90 | 2000 | 20 | 0 | 2020 | \$0.00 | \$2,188,071.98 |
| Other HVAC Systems | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Sprinklers | Critical | \$5.74 | \$8.61 | 217,669 | \$1,874,130.09 | 145 | \$2,717,488.63 | 1970 | 30 | 0 | 2000 | \$2,717,488.63 | \$0.00 |
| Standpipes | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 30 | 0 | 2000 | \$0.00 | \$0.00 |
| Other Fire Protection Systems | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Electrical Service Distribution | Potentially Critical | \$19.41 | \$29.12 | 217,669 | \$6,338,521.28 | 150 | \$9,507,781.92 | 1970 | 30 | 0 | 2000 | \$9,496,303.81 | \$0.00 |
| Lighting and Branch Wiring | Necessary | \$59.69 | \$89.54 | 217,669 | \$19,490,082.26 | 145 | \$28,260,619.28 | 2000 | 30 | 0 | 2030 | \$0.00 | \$44,030,044.84 |
| Communications and Security | Critical | \$14.60 | \$21.90 | 217,669 | \$4,766,951.10 | 145 | \$6,912,079.10 | 2005 | 10 | 0 | 2015 | \$6,893,231.36 | \$23,876.32 |
| Other Electrical or Generator | Critical | \$0.99 | \$1.48 | 217,669 | \$322,150.12 | 145 | \$467,117.67 | 2000 | 20 | 0 | 2020 | \$0.00 | \$541,529.51 |
| Commercial Equipment | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Institutional Equipment | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Vehicular Equipment | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Other Equipment | Recommended | \$0.89 | \$1.34 | 217,669 | \$291,676.46 | 145 | \$422,930.87 | 2009 | 20 | 0 | 2029 | \$0.00 | \$639,725.23 |
| Fixed Furnishings | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 30 | 0 | 2000 | \$0.00 | \$0.00 |
| Special Structures | Recommended | \$0.09 | \$0.14 | 217,669 | \$30,473.66 | 145 | \$44,186.81 | 1980 | 30 | 0 | 2010 | \$44,186.81 | \$0.00 |

FORECAST REPORT: Summary of Backlog and 20 year capital renewal forecast. Subsystem End-Of-Life Cycle Replacement Costs for Stand-Alone Projects are included in the year that the subsystem reaches the end of its Life Cycle. Inflation is assumed to be 3%. This Forecast does not include operational or community needs such as upgrades, improvements, expansions or building replacements. This Forecast is not a funding plan or capital plan. This forecast can be combined with operational or community input to develop an asset management plan.

DEFINITIONS for FORECAST REPORT:

Subsystem: Building and Site assets that are inherent to the building operation such as HVAC provides heating, ventilating, and air conditioning and electrical systems provide power to the building.

Year column 2015: The Backlog of subsystems that have reached the end of their Life Cycle. Subsystems are still in operation and failure becomes more likely as a subsystem passes the end of its Life Cycle.

Year columns 2016 through 2035: The Capital Renewal cost of subsystems that will reach the end of their Life Cycle in the future.

[illegible]

Facility # 000008 Office. City Operations Building. COB. Downtown

| FORECAST REPORT – Building Only | | | | | | | | | | | | | | | | | | | | | |
|---------------------------------|---------------------|------------|-----------------|------------|-----------------|--------------------|------------|------------|-----------------|------------|-----------------|-----------------|------------|------------|------------------|---------------------|-----------------|------------|-----------------|------------|------------|
| Subsystem | 2015(\$) | 2016(\$) | 2017(\$) | 2018(\$) | 2019(\$) | 2020(\$) | 2021(\$) | 2022(\$) | 2023(\$) | 2024(\$) | 2025(\$) | 2026(\$) | 2027(\$) | 2028(\$) | 2029(\$) | 2030(\$) | 2031(\$) | 2032(\$) | 2033(\$) | 2034(\$) | 2035(\$) |
| Other Plumbing Systems | \$0 | \$0 | \$0 | \$0 | \$0 | \$65,862 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Plumbing Fixtures | \$6,717,483 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Rain Water Drainage | \$1,205,669 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Sanitary Waste | \$1,325,604 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| HVAC | \$17,406,942 | \$0 | \$20,940 | \$0 | \$20,025 | \$2,889,176 | \$0 | \$0 | \$9,974 | \$0 | \$65,587 | \$49,249 | \$0 | \$0 | \$244,224 | \$0 | \$22,746 | \$0 | \$83,083 | \$0 | \$0 |
| Controls and Instrumentation | \$0 | \$0 | \$0 | \$0 | \$0 | \$2,188,072 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Cooling Generating Systems | \$122,598 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$244,224 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Distribution Systems | \$17,279,895 | \$0 | \$20,940 | \$0 | \$0 | \$17,044 | \$0 | \$0 | \$9,974 | \$0 | \$65,587 | \$49,249 | \$0 | \$0 | \$0 | \$0 | \$22,746 | \$0 | \$83,083 | \$0 | \$0 |
| Energy Supply | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Heat Generating Systems | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Other HVAC Systems | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Terminal and Package Units | \$4,448 | \$0 | \$0 | \$0 | \$20,025 | \$684,060 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| FIRE PROTECTION | \$2,717,489 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Other Fire Protection Systems | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Sprinklers | \$2,717,489 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Standpipes | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| ELECTRICAL | \$16,389,535 | \$0 | \$0 | \$0 | \$0 | \$541,530 | \$0 | \$0 | \$23,876 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$44,030,045 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Communications and Security | \$6,893,231 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$23,876 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Electrical Service Distribution | \$9,496,304 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Lighting and Branch Wiring | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$44,030,045 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Other Electrical or Generator | \$0 | \$0 | \$0 | \$0 | \$0 | \$541,530 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| EQUIPMENT | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$639,725 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Commercial Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Institutional Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Other Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$639,725 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Vehicular Equipment | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| FURNISHINGS | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Fixed Furnishings | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| SPECIAL CONSTRUCTION | \$44,187 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Special Structures | \$44,187 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |

DEFICIENCY REPORT: Summary of individual deficiencies that are included in the Cost Model Backlog and Capital Renewal costs. This deficiency report does not include operational or community needs such as upgrades, improvements, expansions or building replacements.

DEFINITIONS for DEFICIENCY REPORT (in order presented in spreadsheet):

Year: The year that the subsystem will reach the end of its Life Cycle or the year that the maintenance repairs are assessed. The year for a particular deficiency corresponds with the year in the Forecast Report and the Next Renewal Year in the Cost Model Report.

Priority: The relative urgency of completing the work as compared to other work within the inventory based on the impact of failure of the Subsystem. The categories included from highest priority to lowest priority are Critical, Potentially Critical, Necessary, and Recommended. Critical and Potentially Critical work could affect the health and safety of the building if not corrected. Necessary and Recommended work could result in minor impact to the building if not corrected. The Not Applicable category includes work that is not priority ranked because it is not based on failure and operations impact (eg. accessibility improvements – new toilets, wider access hallways).

Subsystem: Building and Site assets that are inherent to the building operation such as HVAC provides heating, ventilating, and air conditioning and electrical systems provide power to the building.


Correction: A description of the work needed to fix the deficiency. Examples of corrections include Replace, Repair, Clean, Patch, etc.

Photo: Photograph of subsystem. Some photographs are stock photos of typical subsystems.




Location: Location includes Floor location, Room location, ID if available, and Type which indicates component of subsystem with deficiency.

Funding Type: Funding required to correct deficiency. Capital funding is indicated if entire subsystem is to be replaced. Maintenance funding is indicated for partial replacements, repairs, cleaning, patching, etc.




Cost: The cost to correct the deficiency. Costs are included in the Cost Model based on subsystem and the Forecast based on subsystem and year. Current year deficiencies are included in the Capital or Maintenance Backlog.

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|---------------------|------------|--|-------------|--------------|--------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Elevators and Lifts | Replace |  | 1970 System | Capital | \$21,440,921 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-------------|----------------------|------------|---|-------------|--------------|--------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Recommended | Floor Finishes | Replace |  | 1970 System | Capital | \$16,246,752 |
| 2015 | Necessary | Distribution Systems | Replace |  | 1970 System | Capital | \$15,383,765 |
| 2015 | Recommended | Ceiling Finishes | Replace |  | 1970 System | Capital | \$13,641,099 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|---------------------------------|------------|---|-------------|--------------|--------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Recommended | Interior Doors | Replace |  | 1970 System | Capital | \$12,047,665 |
| 2015 | Potentially Critical | Electrical Service Distribution | Replace |  | 1970 System | Capital | \$8,975,392 |
| 2015 | Necessary | Exterior Windows | Replace |  | 1970 System | Capital | \$8,226,037 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|-----------------------------|------------|---|-------------|--------------|-------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Critical | Communications and Security | Replace |  | 1970 System | Capital | \$6,893,231 |
| 2015 | Necessary | Plumbing Fixtures | Replace |  | 1970 System | Capital | \$6,717,483 |
| 2015 | Critical | Sprinklers | Replace |  | 1970 System | Capital | \$2,710,450 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-------------|----------------|------------|---|-------------|--------------|-------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Recommended | Wall Finishes | Replace |  | 1970 System | Capital | \$2,289,663 |
| 2015 | Necessary | Exterior Doors | Replace |  | 1970 System | Capital | \$2,006,874 |
| 2015 | Recommended | Sanitary Waste | Replace |  | 1970 System | Capital | \$1,325,604 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|-----------------------------|------------|---|-------------|--------------|-------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Rain Water Drainage | Replace |  | 1970 System | Capital | \$1,205,669 |
| 2015 | Recommended | Stair Finishes | Replace |  | 1970 System | Capital | \$937,392 |
| 2015 | Potentially Critical | Domestic Water Distribution | Replace |  | 1970 System | Capital | \$858,487 |



Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|----------------------|------------|---|--|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Critical | Roof Coverings | Replace |  | 1970 System | Capital | \$824,043 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Air Handling Units | Capital | \$491,751 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Air Handling Units | Capital | \$491,751 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|---------------------------------|------------|---|---|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Other Conveying Systems | Replace |  | 1970 System | Capital | \$422,931 |
| 2015 | Critical | Roof Coverings | Replace |  | Floor: Roof 2 Room: Roof ID: Type: Modified Bitumen | Capital | \$320,269 |
| 2015 | Potentially Critical | Electrical Service Distribution | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Motor Control Centers | Capital | \$259,373 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|---------------------------------|------------|---|--|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace | | Floor: Roof 1 Room: Penthouse ID: Type: Air Handling Units | Capital | \$199,722 |
| 2015 | Potentially Critical | Electrical Service Distribution | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Motor Control Centers | Capital | \$147,693 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: U-696253 Type: Exhaust Fans | Capital | \$143,900 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|---------------------------------|------------|---|---|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: U-696253 Type: Exhaust Fans | Capital | \$143,900 |
| 2015 | Potentially Critical | Electrical Service Distribution | Replace |  | Floor: B1 Room: Main Elec Room ID: SNE25574-1F Type: Electrical Panel | Capital | \$113,845 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Mech Room ID: Type: Air Handling Units | Capital | \$108,407 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|----------------------------|------------|---|---|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Mech Room 2 ID: Type: Air Handling Units | Capital | \$108,407 |
| 2015 | Potentially Critical | Cooling Generating Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Cooling Towers | Capital | \$88,425 |
| 2015 | Recommended | Special Structures | Replace |  | 1970 System | Capital | \$44,187 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|----------------------------|------------|---|---|--------------|----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Potentially Critical | Cooling Generating Systems | Replace |  | 1970 System | Capital | \$34,174 |
| 2015 | Critical | Roof Coverings | Replace |  | Floor: Roof 1 Room: Roof ID: Type: Modified Bitumen | Capital | \$33,713 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: U-696251 Type: Exhaust Fans | Capital | \$23,740 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-------------|----------------------|--------------------|---|---|--------------|----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: 696252 Type: Exhaust Fans | Capital | \$23,740 |
| 2015 | Recommended | Wall Finishes | Remove and Replace |  | Floor: 1 Room: Lobby | Maintenance | \$23,640 |
| 2015 | Recommended | Exterior Windows | Renew Finishes |  | Floor: Roof 1 Room: Roof | Maintenance | \$22,177 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-------------|----------------------|--------------------|---|--|--------------|----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Recommended | Exterior Doors | Remove and Replace |  | Floor: 1 Room: Fire Staion | Maintenance | \$21,471 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: 4UG0298 Type: Exhaust Fans | Capital | \$14,175 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Exhaust Fans | Capital | \$14,175 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|----------------------|------------|---|---|--------------|----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Cooling Tower Water Pumps | Capital | \$12,568 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Cooling Tower Water Pumps | Capital | \$12,568 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Exhaust Fans | Capital | \$12,025 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|----------------------|------------|---|--|--------------|----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Mech Room ID: Type: Exhaust Fans | Capital | \$10,144 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Mech Room 2 ID: Type: Chilled Water Pumps | Capital | \$9,891 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Mech Room 2 ID: Type: Chilled Water Pumps | Capital | \$9,891 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|----------------------|------------|---|---|--------------|---------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Chilled Water Pumps | Capital | \$9,891 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: Roof 1 Room: Penthouse ID: Type: Chilled Water Pumps | Capital | \$9,891 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Basement ID: 191588 Type: Exhaust Fans | Capital | \$9,532 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|----------------------|------------|---|--|--------------|---------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Basement ID: Type: Fan Coil Units | Capital | \$7,874 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Basement ID: Type: Exhaust Fans | Capital | \$7,798 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: 1 Room: Fire Station Bay ID: Type: Exhaust Fans | Capital | \$7,798 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-------------|------------------|----------------|---|--|--------------|---------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Critical | Sprinklers | Replace |  | Floor: B1 Room: Basement ID: Type: Fire Suppression Valve | Capital | \$7,039 |
| 2015 | Recommended | Wall Finishes | Repair |  | Floor: 6 Room: Mechanical Penthouse | Maintenance | \$6,504 |
| 2015 | Recommended | Exterior Windows | Renew Finishes |  | Floor: 1 Room: Fire Staion | Maintenance | \$5,795 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|----------------------------|------------|---|--|--------------|---------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: 5 Room: Phone Room ID: 152857 Type: Exhaust Fans | Capital | \$5,496 |
| 2015 | Potentially Critical | Terminal and Package Units | Replace |  | Floor: 1 Room: Loading Dock ID: Type: Air Cooled Condensing Units | Capital | \$4,448 |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: 1 Room: Fire Station Bay ID: Type: Exhaust Fans | Capital | \$3,549 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-------------|----------------------|----------------|---|---|--------------|---------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Distribution Systems | Replace |  | Floor: 1 Room: Fire Station Bay ID: Type: Exhaust Fans | Capital | \$3,549 |
| 2015 | Recommended | Floor Finishes | Clean |  | Floor: 1 Room: Lobby | Maintenance | \$1,368 |
| 2015 | Recommended | Exterior Doors | Renew Finishes |  | Floor: Roof 1 Room: Roof | Maintenance | \$1,127 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|----------------------|------------|---|---|--------------|---------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Necessary | Interior Doors | Repair |  | Floor: 1 Room: Fire Station Offices | Maintenance | \$314 |
| 2017 | Necessary | Distribution Systems | Replace |  | Floor: 5 Room: Data Room ID: Type: Fan Coil Units | Capital | \$5,350 |
| 2017 | Necessary | Distribution Systems | Replace |  | Floor: 5 Room: Data Room ID: Type: Fan Coil Units | Capital | \$5,350 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|----------------------------|------------|---|---|--------------|---------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2017 | Necessary | Distribution Systems | Replace |  | Floor: 5 Room: Phone Room ID: Type: Fan Coil Units | Capital | \$5,350 |
| 2017 | Necessary | Distribution Systems | Replace |  | Floor: 5 Room: Data Room ID: Type: Fan Coil Units | Capital | \$4,891 |
| 2019 | Potentially Critical | Terminal and Package Units | Replace |  | Floor: 5 Room: Elevator Lobby ID: Type: Air Cooled Condensing Units | Capital | \$5,006 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|----------------------------|------------|-------|---|--------------|---------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2019 | Potentially Critical | Terminal and Package Units | Replace | | Floor: 5 Room: Elevator Lobby ID: Type: Air Cooled Condensing Units | Capital | \$5,006 |
| 2019 | Potentially Critical | Terminal and Package Units | Replace | | Floor: 5 Room: Elevator Lobby ID: Type: Air Cooled Condensing Units | Capital | \$5,006 |
| 2019 | Potentially Critical | Terminal and Package Units | Replace | | Floor: 5 Room: Elevator Lobby ID: Type: Air Cooled Condensing Units | Capital | \$5,006 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|------------------------------|------------|---|---|--------------|-------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2020 | Necessary | Controls and Instrumentation | Replace |  | 1970 System | Capital | \$2,188,072 |
| 2020 | Potentially Critical | Terminal and Package Units | Replace |  | 1970 System | Capital | \$684,060 |
| 2020 | Necessary | Elevators and Lifts | Replace |  | Floor: Roof 1 Room: Elevator Machine Room ID: 2-40152-57 Type: Elevators | Capital | \$422,921 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|-------------------------------|------------|---|---|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2020 | Necessary | Elevators and Lifts | Replace |  | Floor: Roof 1 Room: Elevator Machine Room ID: 2-4052-17 Type: Elevators | Capital | \$421,156 |
| 2020 | Necessary | Elevators and Lifts | Replace |  | Floor: Roof 1 Room: Elevator Machine Room ID: 2-40152-57 Type: Elevators | Capital | \$421,156 |
| 2020 | Critical | Other Electrical or Generator | Replace |  | 1970 System | Capital | \$395,241 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-------------|-------------------------------|------------|---|---|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2020 | Necessary | Elevators and Lifts | Replace |  | Floor: B1 Room: Basement ID: Type: Elevators | Capital | \$320,644 |
| 2020 | Critical | Other Electrical or Generator | Replace |  | Floor: B1 Room: Generator Room ID: S423331 Type: Generators | Capital | \$146,289 |
| 2020 | Recommended | Other Plumbing Systems | Replace |  | 1970 System | Capital | \$65,862 |




Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|-----------------------------|------------|---|---|--------------|----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2020 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Generator Room ID: 152855 Type: Exhaust Fans | Capital | \$11,050 |
| 2020 | Necessary | Distribution Systems | Replace |  | Floor: 5 Room: Data Room ID: 152856 Type: Exhaust Fans | Capital | \$5,994 |
| 2023 | Critical | Communications and Security | Replace |  | Floor: B1 Room: Basement ID: 5831283014 Type: Fire Alarm System | Capital | \$23,876 |



Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|----------------------|------------|---|--|--------------|----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2023 | Necessary | Distribution Systems | Replace |  | Floor: Roof 2 Room: Roof ID: 11697785 0903 Type: Exhaust Fans | Capital | \$9,974 |
| 2025 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Data Room 2 ID: Type: Air Handling Units | Capital | \$65,587 |
| 2026 | Necessary | Distribution Systems | Replace |  | Floor: 1 Room: Fire Station Bay ID: Type: Vehicle Exhaust System | Capital | \$48,682 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|----------------------|----------------------------|------------|---|--|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2026 | Necessary | Distribution Systems | Replace |  | Floor: 1 Room: Fire Station Bay ID: Type: Exhaust Fans | Capital | \$567 |
| 2029 | Recommended | Other Equipment | Replace |  | 1970 System | Capital | \$639,725 |
| 2029 | Potentially Critical | Cooling Generating Systems | Replace |  | Floor: 1 Room: Fire Station Bay ID: C99G14091M Type: Chillers | Capital | \$244,224 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Building Only | | | | | | | |
|-----------------------------------|-----------|----------------------------|------------|---|---|--------------|--------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2030 | Necessary | Lighting and Branch Wiring | Replace |  | 1970 System | Capital | \$44,030,045 |
| 2031 | Necessary | Distribution Systems | Replace | | Floor: Roof 1 Room: Penthouse ID: 12384840 Type: Exhaust Fans | Capital | \$22,746 |
| 2033 | Necessary | Distribution Systems | Replace |  | Floor: B1 Room: Data Room ID: Type: Air Handling Units | Capital | \$83,083 |

EQUIPMENT INVENTORY REPORT: List Of equipment that is installed as part of the existing subsystems. Estimated Replacement Costs are for the equipment only and are included in the subsystem replacement costs in the Cost Model.

DEFINITIONS for EQUIPMENT INVENTORY (in order presented in spreadsheet):

Subsystem: Building and Site assets that are inherent to the building operation such as HVAC provides heating, ventilating, and air conditioning and electrical systems provide power to the building.

Space: Location of equipment.

Equipment Number: City-issued number on some equipment such as HVAC units on some buildings.

Equipment Type: The type of equipment such as Air Handling Unit, Exhaust Fan, Domestic Water Pump, etc.

Manufacturer, Model Number, Serial Number: Information from the tag if there was a readable tag during the assessment. Some equipment such as Roof Coverings do not have tag information.

Capacity: Size or output of equipment if known. UNK stands for unknown and indicates that the size was not visible in the field.

UOM: Unit of Measure that describes the data in Capacity column such as HP for Horse Power of pump, TON for air condition tonnage, AMP for electrical breaker amperage, etc.

Year Installed: Estimated year equipment was installed based on year building was installed or year equipment was estimated to be replaced based on records available during assessment and staff interviews.






Next Renewal Year: The year that the subsystem will reach the end of its life cycle. Calculated by adding the Life Cycle to the Last Renovation Year.

Estimated Replacement Cost: Cost to replace the equipment only not the entire subsystem. The equipment costs are included in the Cost Model's Subsystem Replacement Costs and in the Forecast Needs Costs







Funding Type: Funding required to correct deficiency. Capital funding is indicated if entire subsystem is to be replaced. Maintenance funding is indicated for partial replacements, repairs, cleaning, patching, etc.

Photo: Photograph of equipment. Some photographs are stock photos of typical equipment.

Assessor Notes: Additional notes by assessor which may indicate more details about location, tag, or condition.

| EQUIPMENT INVENTORY REPORT – Building Only | | | | | | | | | | | | | | |
|--|-----------|------------------|----------------|----------------------|--------------|---------------|----------|-----|----------------|-------------------|----------------------------|--------------|---|--|
| Subsystem | Space | Equipment Number | Equipment Type | Manufacturer | Model Number | Serial Number | Capacity | UOM | Year Installed | Next Renewal Year | Estimated Replacement Cost | Funding Type | Photo | Assessor Notes |
| Distribution Systems | Basement | SA 101 | Fan Coil Units | MCQUAY INTERNATIONAL | | | 0.5 | HP | 1970 | 1988 | \$7,874 | Capital |  | OSA SUPPLY FAN. P559. |
| Distribution Systems | Basement | EF 7 | Exhaust Fans | | | | UNK | | 1970 | 1990 | \$7,798 | Capital |  | INLINE. P557. |
| Distribution Systems | Mech Room | F 3 | Exhaust Fans | | | | 5 | HP | 1970 | 1990 | \$10,144 | Capital |  | RA FAN FOR AH-2. P572. |
| Distribution Systems | Penthouse | RF 2 | Exhaust Fans | SHELDONS | 445 | U-696251 | 20 | HP | 1970 | 1990 | \$23,740 | Capital |  | RETURN AIR FAN. SERVES AHU. P486. VFD. |
| Distribution Systems | Penthouse | SF 1 | Exhaust Fans | SHELDONS | 365 | U-696253 | 75 | HP | 1970 | 1990 | \$143,900 | Capital |  | SUPPLY FAN SERVING AHU. MOTOR RENEWED 2010(EST.). P473. VFD. |











Facility # 000008 Office. City Operations Building. COB. Downtown

| EQUIPMENT INVENTORY REPORT – Building Only | | | | | | | | | | | | | | |
|--|-------------|------------------|---------------------------|----------------|--------------|---------------|----------|-----|----------------|-------------------|----------------------------|--------------|---|---|
| Subsystem | Space | Equipment Number | Equipment Type | Manufacturer | Model Number | Serial Number | Capacity | UOM | Year Installed | Next Renewal Year | Estimated Replacement Cost | Funding Type | Photo | Assessor Notes |
| Distribution Systems | Penthouse | EF 1 | Exhaust Fans | SNYDER GENERAL | 22 B1 CW | 4UG0298 | UNK | | 1970 | 1990 | \$14,175 | Capital |  | PART ID 927535-01. P502. |
| Distribution Systems | Penthouse | F 1 | Exhaust Fans | SHELDONS | 445 | 696252 | 20 | HP | 1970 | 1990 | \$23,740 | Capital |  | RETURN AIR FAN. P461. VFD. |
| Distribution Systems | Penthouse | SF 2 | Exhaust Fans | SHELDONS | 365 | U-696253 | 75 | HP | 1970 | 1990 | \$143,900 | Capital |  | SUPPLY FAN FOR AHU. MOTOR REPLACED 2010 (EST). P481. VFD. |
| Distribution Systems | Penthouse | EF 5 | Exhaust Fans | | | | UNK | | 1970 | 1990 | \$14,175 | Capital |  | NORTH INTETIOR EXHAUST. P490. |
| Sprinklers | Basement | Not Labeled | Fire Suppression Valve | KENNEDY | 175W | | UNK | | 1970 | 1990 | \$7,039 | Capital |  | 8 IN, P601 |
| Distribution Systems | Penthouse | Not Labeled | Cooling Tower Water Pumps | | | | UNK | | 1970 | 1995 | \$12,568 | Capital |  | NOT IN USE. ABANDONED CP. P504. |
| Distribution Systems | Penthouse | Not Labeled | Cooling Tower Water Pumps | | | | UNK | | 1970 | 1995 | \$12,568 | Capital |  | NOT IN USE. ABANDONED CP. P503. |
| Distribution Systems | Mech Room | AH 2 | Air Handling Units | | | | 7.5 | HP | 1970 | 1995 | \$108,407 | Capital |  | CW. P571. |
| Distribution Systems | Mech Room 2 | AH 1 | Air Handling Units | | | | UNK | | 1970 | 1995 | \$108,407 | Capital |  | CW. VFD. P593. MOTOR REPLACED. |
| Distribution Systems | Penthouse | Not Labeled | Air Handling Units | | | | UNK | | 1970 | 1995 | \$491,751 | Capital |  | BUILT-UP AHU. VFD. SERVED BY SF-2 & RF-2. CW/HW. P499. |
| Distribution Systems | Penthouse | Not Labeled | Air Handling Units | | | | UNK | | 1970 | 1995 | \$199,722 | Capital | | NOT IN USE. ABANDONED CP. |








Facility # 000008 Office. City Operations Building. COB. Downtown

| EQUIPMENT INVENTORY REPORT – Building Only | | | | | | | | | | | | | | |
|--|----------------|------------------|-----------------------|--------------------|--------------|---------------|----------|-----|----------------|-------------------|----------------------------|--------------|---|---|
| Subsystem | Space | Equipment Number | Equipment Type | Manufacturer | Model Number | Serial Number | Capacity | UOM | Year Installed | Next Renewal Year | Estimated Replacement Cost | Funding Type | Photo | Assessor Notes |
| Distribution Systems | Penthouse | Not Labeled | Air Handling Units | | | | UNK | | 1970 | 1995 | \$491,751 | Capital |  | BUILT-UP AHU. SERVED BY SF-1 & F-1. CW/HW. P474. VFD. |
| Distribution Systems | Mech Room 2 | P 6A | Chilled Water Pumps | BELL AND GOSSETT | | | 3 HP | | 1970 | 1995 | \$9,891 | Capital |  | NOT IN USE. POOR CONDITION. P598. |
| Distribution Systems | Mech Room 2 | P 5A | Chilled Water Pumps | BELL AND GOSSETT | 5792906L | | 3 HP | | 1970 | 1995 | \$9,891 | Capital |  | NOT IN USE. POOR CONDITION. P597. |
| Distribution Systems | Penthouse | 33 | Chilled Water Pumps | | | | UNK | | 1970 | 1995 | \$9,891 | Capital |  | NOT IN SERVICE. ABANDONED CO. P510. |
| Distribution Systems | Penthouse | 32 | Chilled Water Pumps | | | | UNK | | 1970 | 1995 | \$9,891 | Capital |  | NOT IN USE. ABANDONED CP. P509. |
| Electrical Service Distribution | Penthouse | Not Labeled | Motor Control Centers | WESTINGHO USE | SNC-25574-2 | | 600 | AMP | 1970 | 1995 | \$147,693 | Capital |  | INCLUDED TRANSFER SWITCH SECTION. P259. |
| Electrical Service Distribution | Penthouse | Not Labeled | Motor Control Centers | WESTINGHO USE | SNC 25574-2 | | 600 | AMP | 1970 | 1995 | \$259,373 | Capital |  | P507 |
| Cooling Generating Systems | Penthouse | Not Labeled | Cooling Towers | | | | UNK | | 1970 | 2000 | \$88,425 | Capital |  | NOT IN USE. ROTTED. RUSTED/CORRODED. ABANDONED CP. P506. |
| Electrical Service Distribution | Main Elec Room | Not Labeled | Electrical Panel | WESTINGHO USE | | SNE25574-1F | 3000 | AMP | 1970 | 2000 | \$113,845 | Capital |  | SUBSTATION, OIL FILL XFMR, 12 KV PRIMARY, 2000 KVA. P575. |
| Distribution Systems | Penthouse | EF 3 | Exhaust Fans | PHILIPPS | FGP15-9 | | 3 | HP | 1988 | 2008 | \$12,025 | Capital |  | P501 |
| Distribution Systems | Basement | Not Labeled | Exhaust Fans | GREENHECK FAN CORP | SQB-24-30 | 191588 | 3 | HP | 1990 | 2010 | \$9,532 | Capital |  | EST DATE. P568 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| EQUIPMENT INVENTORY REPORT – Building Only | | | | | | | | | | | | | | |
|--|------------------|------------------|-----------------------------|--------------------|--------------|---------------|----------|-----|----------------|-------------------|----------------------------|--------------|---|---|
| Subsystem | Space | Equipment Number | Equipment Type | Manufacturer | Model Number | Serial Number | Capacity | UOM | Year Installed | Next Renewal Year | Estimated Replacement Cost | Funding Type | Photo | Assessor Notes |
| Distribution Systems | Fire Station Bay | Fan 1 | Exhaust Fans | | | | UNK | | 1990 | 2010 | \$3,549 | Capital |  | WALL MNT. EST DATE. P542. |
| Distribution Systems | Fire Station Bay | Not Labeled | Exhaust Fans | | | | UNK | | 1990 | 2010 | \$7,798 | Capital |  | INLINE EF FOR FUEL SYSTEM. EST DATE. P540. |
| Distribution Systems | Fire Station Bay | Fan 2 | Exhaust Fans | | | | UNK | | 1990 | 2010 | \$3,549 | Capital |  | WALL MNT. EST DATE. P542. |
| Distribution Systems | Phone Room | Not Labeled | Exhaust Fans | GREENHECK FAN CORP | 508-1D4 | 152857 | 0.25 | | 1990 | 2010 | \$5,496 | Capital |  | EST DATE. P606. |
| Roof Coverings | Roof | Not Labeled | Modified Bitumen | | | | UNK | | 1995 | 2010 | \$33,713 | Capital |  | P456. |
| Terminal and Package Units | Loading Dock | Not Labeled | Air Cooled Condensing Units | CARRIER | | | UNK | | 1990 | 2010 | \$4,448 | Capital |  | EST DATE. MINI SPLIT. MATCHING FCU NOT FOUND. P611. |
| Roof Coverings | Roof | Not Labeled | Modified Bitumen | | | | UNK | | 2000 | 2015 | \$320,269 | Capital |  | GRANULAR SURFACE. P492. |
| Distribution Systems | Data Room | Not Labeled | Fan Coil Units | QUIETSIDe | | | UNK | | 1999 | 2017 | \$4,610 | Capital |  | MINI SPLIT. P604. EST DATE. |
| Distribution Systems | Data Room | Not Labeled | Fan Coil Units | COAIRE | CIC-18M2Z | | UNK | | 1999 | 2017 | \$5,043 | Capital |  | EST DATE. MINI SPLIT. P607. |
| Distribution Systems | Data Room | Not Labeled | Fan Coil Units | EMI | | | UNK | | 1999 | 2017 | \$5,043 | Capital |  | EST DATE. MINI SPLIT. P610. |
| Distribution Systems | Phone Room | Not Labeled | Fan Coil Units | EMI | | | UNK | | 1999 | 2017 | \$5,043 | Capital |  | EST. DATE. MINI SPLIT. P520. |

Facility # 000008 Office. City Operations Building. COB. Downtown

| EQUIPMENT INVENTORY REPORT – Building Only | | | | | | | | | | | | | | |
|--|-----------------------|------------------|-----------------------------|----------------------|--------------|---------------|----------|-----|----------------|-------------------|----------------------------|--------------|---|--|
| Subsystem | Space | Equipment Number | Equipment Type | Manufacturer | Model Number | Serial Number | Capacity | UOM | Year Installed | Next Renewal Year | Estimated Replacement Cost | Funding Type | Photo | Assessor Notes |
| Terminal and Package Units | Elevator Lobby | Not Labeled | Air Cooled Condensing Units | | | | UNK | | 1999 | 2019 | \$4,448 | Capital |  | EST DATE. ABOVE CEILING, NOT OBSERVED. |
| Terminal and Package Units | Elevator Lobby | Not Labeled | Air Cooled Condensing Units | | | | UNK | | 1999 | 2019 | \$4,448 | Capital | | EST DATE. ABOVE CEILING. NOT OBSERVED |
| Terminal and Package Units | Elevator Lobby | Not Labeled | Air Cooled Condensing Units | | | | UNK | | 1999 | 2019 | \$4,448 | Capital | | ABOVE CEILING. NOT OBSERVED. |
| Terminal and Package Units | Elevator Lobby | Not Labeled | Air Cooled Condensing Units | EMI | | | UNK | | 1999 | 2019 | \$4,448 | Capital | | LOCATED ABOVE CEILING. P530. |
| Distribution Systems | Data Room | Not Labeled | Exhaust Fans | | S0B104 | 152856 | 0.25 | HP | 2000 | 2020 | \$5,170 | Capital |  | INLINE. P522. EST. DATE. |
| Distribution Systems | Generator Room | Not Labeled | Exhaust Fans | GREENHECK FAN CORP | SQB-2415 | 152855 | 1 | HP | 2000 | 2020 | \$9,532 | Capital |  | EST DATE. COMBUSTION AIR SF FOR GENERATOR. P565. |
| Elevators and Lifts | Basement | Not Labeled | Elevators | ARMOR ELEVATOR CO | | | UNK | | 1970 | 2020 | \$276,585 | Capital |  | LOADING DOCK ELEVATOR. 2 LANDINGS, 5000 LBS. P581. |
| Elevators and Lifts | Elevator Machine Room | 3 | Elevators | HAUGHTON ELEVATOR CO | EK | 2-4052-17 | 25 | HP | 1970 | 2020 | \$363,284 | Capital |  | 2500 LBS. 6 LANDINGS. P468. |
| Elevators and Lifts | Elevator Machine Room | 2 | Elevators | HAUGHTON ELEVATOR CO | EK | 2-40152-57 | 30 | HP | 1970 | 2020 | \$364,807 | Capital |  | 3000 LBS. 6 LANDINGS. P467. |
| Elevators and Lifts | Elevator Machine Room | 1 | Elevators | HAUGHTON ELEVATOR CO | EK | 2-40152-57 | 25 | HP | 1970 | 2020 | \$363,284 | Capital |  | 2500 LBS. 6 LANDINGS. P466. |
| Other Electrical or Generator | Generator Room | Not Labeled | Generators | SOLAR/IH | T35IN | S423331 | 225 | KW | 2000 | 2020 | \$126,187 | Capital |  | P560. |

Facility # 000008 Office. City Operations Building. COB. Downtown

| EQUIPMENT INVENTORY REPORT – Building Only | | | | | | | | | | | | | | |
|--|------------------|------------------|-------------------------------------|-------------------------|---------------|---------------|----------|-----|----------------|-------------------|----------------------------|--------------|---|---|
| Subsystem | Space | Equipment Number | Equipment Type | Manufacturer | Model Number | Serial Number | Capacity | UOM | Year Installed | Next Renewal Year | Estimated Replacement Cost | Funding Type | Photo | Assessor Notes |
| Communications and Security | Basement | Not Labeled | Fire Alarm System | FIKE PROTECTION SYSTEMS | 10-051-R-1 | 5831283014 | UNK | | 2008 | 2023 | \$18,848 | Capital |  | FM-200 SYSTEM SERVING DATA RM ONLY. EST. DATE. P584. DRY CHEM |
| Distribution Systems | Roof | Not Labeled | Exhaust Fans | DAYTON | 4YY18 | 11697785 0903 | UNK | | 2003 | 2023 | \$7,874 | Capital |  | EST. DATE. UPBLAST. P498 |
| Distribution Systems | Data Room 2 | Not Labeled | Air Handling Units | COMPU-AIRE | | | UNK | | 2000 | 2025 | \$48,803 | Capital |  | EST DATE. CW. P587. |
| Distribution Systems | Fire Station Bay | Not Labeled | Vehicle Exhaust System | AIRMATION | AMARB-302ND | | 7.5 | HP | 2006 | 2026 | \$35,170 | Capital |  | EST. DATE. 14 TOTAL UNITS. P527. |
| Distribution Systems | Fire Station Bay | Not Labeled | Exhaust Fans | | | | UNK | | 2006 | 2026 | \$410 | Capital |  | R/R CEILING EF. P539. |
| Cooling Generating Systems | Fire Station Bay | Not Labeled | Chillers | TRANE | CGAFC6O4AC A1 | C99G14091M | 60 | TON | 1999 | 2029 | \$161,460 | Capital |  | EST DATE. P541. CONDENSER DISCHARGES INTO INTERIOR SPACE. |
| Distribution Systems | Penthouse | Not Labeled | Exhaust Fans | ACCUREX | XIB200-30-X | 12384840 | UNK | | 2011 | 2031 | \$14,175 | Capital | | EST. DATE. |
| Distribution Systems | Data Room | Not Labeled | Air Handling Units | POMONA AIR | | | UNK | | 2008 | 2033 | \$48,803 | Capital |  | CW. P585. EST DATE. |
| Electrical Service Distribution | Elec Closet | TSC | Automatic Transfer Switch | ZENITH | ZG3SA02041 | 1632707-1 | 200 | AMP | 2012 | 2037 | \$11,478 | Capital |  | P589. |
| Exterior Doors | Fire Staion | None | Apparatus Doors. Fire Stations Only | CORNELL | sgh 150/21 | | UNK | | 2006 | 2046 | \$50,011 | Capital |  | 3 motor operated overhad roll-up doors. P. 535 |
| Exterior Doors | Fire Staion | None | Apparatus Doors. Fire Stations Only | POWER MASTER | | | UNK | | 2006 | 2046 | \$16,670 | Capital |  | 1 motor operated steel roll-up door. P. 543 |

Facility # 000008 Office. City Operations Building. COB. Downtown

COST MODEL REPORT: Summary of existing Subsystem values and Life Cycle information. Cost Model data does not include operational or community needs such as upgrades, improvements, expansions or building replacements.

DEFINITIONS for COST MODEL REPORT (in order presented in spreadsheet):

Subsystem: Building and Site assets that are inherent to the building operation such as HVAC provides heating, ventilating, and air conditioning and electrical systems provide power to the building.

Priority: The relative importance of correcting the deficiency (ie replacing the subsystem or performing maintenance repairs). The priority levels used in this condition assessment are Critical, Potentially Critical, Necessary, Recommended, and Not Applicable.

Cost per Square Foot: Cost per square foot of building area to replace a subsystem including hard costs (direct construction costs such as labor, materials, and equipment).

Total Cost per Square Foot: Cost per square foot of building area to replace a subsystem including hard costs and soft costs (indirect costs such as professional services, financing, taxes, etc.)

Gross Square Feet (GSF): The enclosed floor area in a building or under a structure measured to the outside of the structure.

Replacement Cost in New Facility: Cost to replace a subsystem as part of replacing the entire facility with a new facility including hard costs and soft costs.

Percent Renewed: An additional replacement cost that applies to stand-alone projects in existing buildings which accounts for disruption and repair of nearby subsystems. Example: when replacing a roof covering, work is also required on hvac units, electrical, plumbing, rainwater drains, etc.

Replacement Cost for Stand-Alone Projects: Cost to replace a subsystem as a stand-alone project in an existing facility.

Last Renovation Year: The year the subsystem was replaced or the original installation year if not renovated.

Life Cycle: The period of time that a building, system or element can be expected to adequately serve its intended function. Life Cycles for each subsystem are adopted from Building Owners and Managers Association (BOMA) International publication "How to Design and Manage Your Preventive Maintenance Program" Copyright 1996.

Override Default Renewal Year: The year that the subsystem will reach the end of its life cycle as overridden by the assessor. This override is used by the assessor in cases where the subsystem is anticipated to operate shorter or longer than its life cycle.

Next Renewal Year: The year that the subsystem will reach the end of its life cycle. Calculated by adding the Life Cycle to the Last Renovation Year.

Backlog: The cost to correct maintenance or life cycle subsystem deficiencies. Backlog costs do not include future needs, capital renewal, improvements, expansion, or upgrades.

Capital Renewal: The cost to replace a subsystem that will reach the end of its life cycle in future years according to the anticipated life cycle.

Facility # 000008 Office. City Operations Building. COB. Downtown

| COST MODEL REPORT – Site Only | | | | | | | | | | | | | |
|----------------------------------|----------------|----------------------|----------------------------|-------------------|--|-----------------|---|----------------|------------|-------------------------------|-------------------|----------------|-----------------|
| Subsystem | Priority | Cost Per Square Foot | Total Cost Per Square Foot | Gross Square Feet | Replacement Cost in New Facility (Plant Replacement Value) | Percent Renewed | Replacement Cost for Stand-Alone projects | Last Reno Year | Life Cycle | Override Default Renewal Year | Next Renewal Year | Backlog | Capital Renewal |
| Totals | | \$10.14 | \$15.21 | 217,669 | \$3,310,745.49 | | \$4,871,541.06 | | | | | \$3,671,423.03 | \$1,072,965.28 |
| Site Earthwork | Recommended | \$0.36 | \$0.54 | 217,669 | \$117,541.26 | 145 | \$170,434.83 | 1970 | 100 | 0 | 2070 | \$0.00 | \$0.00 |
| Roadways | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 155 | \$0.00 | 0 | 50 | 0 | 2020 | \$0.00 | \$0.00 |
| Parking Lots | Recommended | \$1.47 | \$2.20 | 217,669 | \$478,871.80 | 155 | \$742,251.29 | 1970 | 50 | 2014 | 2014 | \$742,251.29 | \$0.00 |
| Pedestrian Paving | Recommended | \$0.89 | \$1.34 | 217,669 | \$291,676.46 | 155 | \$452,098.51 | 1970 | 50 | 0 | 2020 | \$0.00 | \$524,117.80 |
| Site Development | Recommended | \$1.61 | \$2.42 | 217,669 | \$526,758.98 | 145 | \$763,800.52 | 1970 | 30 | 0 | 2000 | \$763,800.52 | \$0.00 |
| Landscaping | Recommended | \$0.19 | \$0.28 | 217,669 | \$60,947.32 | 135 | \$82,278.88 | 1970 | 10 | 0 | 1980 | \$82,278.88 | \$0.00 |
| Water Supply | Recommended | \$0.30 | \$0.45 | 217,669 | \$97,951.05 | 145 | \$142,029.02 | 1970 | 50 | 0 | 2020 | \$0.00 | \$164,654.24 |
| Sanitary Sewer | Recommended | \$0.70 | \$1.05 | 217,669 | \$228,552.45 | 145 | \$331,401.05 | 1970 | 50 | 0 | 2020 | \$0.00 | \$384,193.24 |
| Storm Sewer | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 1970 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Heating Distribution | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Cooling Distribution | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Fuel Distribution | Recommended | \$0.22 | \$0.33 | 217,669 | \$71,830.77 | 145 | \$104,154.62 | 1990 | 50 | 0 | 2040 | \$0.00 | \$0.00 |
| Electrical Distribution | Recommended | \$2.91 | \$4.36 | 217,669 | \$949,036.84 | 145 | \$1,376,103.42 | 1970 | 30 | 0 | 2000 | \$1,376,103.42 | \$0.00 |
| Site Lighting | Recommended | \$0.61 | \$0.92 | 217,669 | \$200,255.48 | 145 | \$290,370.45 | 1970 | 30 | 0 | 2000 | \$290,370.45 | \$0.00 |
| Site Communications and Security | Recommended | \$0.88 | \$1.32 | 217,669 | \$287,323.08 | 145 | \$416,618.47 | 2000 | 10 | 0 | 2010 | \$416,618.47 | \$0.00 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| COST MODEL REPORT – Site Only | | | | | | | | | | | | | |
|--------------------------------|----------------|----------------------|----------------------------|-------------------|--|-----------------|---|----------------|------------|-------------------------------|-------------------|---------|-----------------|
| Subsystem | Priority | Cost Per Square Foot | Total Cost Per Square Foot | Gross Square Feet | Replacement Cost in New Facility (Plant Replacement Value) | Percent Renewed | Replacement Cost for Stand-Alone projects | Last Reno Year | Life Cycle | Override Default Renewal Year | Next Renewal Year | Backlog | Capital Renewal |
| Service and Pedestrian Tunnels | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |
| Other Site Construction | Not Applicable | \$0.00 | \$0.00 | 217,669 | \$0.00 | 145 | \$0.00 | 0 | 0 | 0 | 1970 | \$0.00 | \$0.00 |

FORECAST REPORT: Summary of Backlog and 20 year capital renewal forecast. Subsystem End-Of-Life Cycle Replacement Costs for Stand-Alone Projects are included in the year that the subsystem reaches the end of its Life Cycle. Inflation is assumed to be 3%. This Forecast does not include operational or community needs such as upgrades, improvements, expansions or building replacements. This Forecast is not a funding plan or capital plan. This forecast can be combined with operational or community input to develop an asset management plan.

DEFINITIONS for FORECAST REPORT:

Subsystem: Building and Site assets that are inherent to the building operation such as HVAC provides heating, ventilating, and air conditioning and electrical systems provide power to the building.

Year column 2015: The Backlog of subsystems that have reached the end of their Life Cycle. Subsystems are still in operation and failure becomes more likely as a subsystem passes the end of its Life Cycle.

Year columns 2016 through 2035: The Capital Renewal cost of subsystems that will reach the end of their Life Cycle in the future.

[illegible]

DEFICIENCY REPORT: Summary of individual deficiencies that are included in the Cost Model Backlog and Capital Renewal costs. This deficiency report does not include operational or community needs such as upgrades, improvements, expansions or building replacements.

DEFINITIONS for DEFICIENCY REPORT (in order presented in spreadsheet):

Year: The year that the subsystem will reach the end of its Life Cycle or the year that the maintenance repairs are assessed. The year for a particular deficiency corresponds with the year in the Forecast Report and the Next Renewal Year in the Cost Model Report.

Priority: The relative urgency of completing the work as compared to other work within the inventory based on the impact of failure of the Subsystem. The categories included from highest priority to lowest priority are Critical, Potentially Critical, Necessary, and Recommended. Critical and Potentially Critical work could affect the health and safety of the building if not corrected. Necessary and Recommended work could result in minor impact to the building if not corrected. The Not Applicable category includes work that is not priority ranked because it is not based on failure and operations impact (eg. accessibility improvements – new toilets, wider access hallways).

Subsystem: Building and Site assets that are inherent to the building operation such as HVAC provides heating, ventilating, and air conditioning and electrical systems provide power to the building.


Correction: A description of the work needed to fix the deficiency. Examples of corrections include Replace, Repair, Clean, Patch, etc.

Photo: Photograph of subsystem. Some photographs are stock photos of typical subsystems.




Location: Location includes Floor location, Room location, ID if available, and Type which indicates component of subsystem with deficiency.

Funding Type: Funding required to correct deficiency. Capital funding is indicated if entire subsystem is to be replaced. Maintenance funding is indicated for partial replacements, repairs, cleaning, patching, etc.




Cost: The cost to correct the deficiency. Costs are included in the Cost Model based on subsystem and the Forecast based on subsystem and year. Current year deficiencies are included in the Capital or Maintenance Backlog.

| DEFICIENCY REPORT – Site Only | | | | | | | |
|-------------------------------|-------------|-------------------------|------------|--|-------------|--------------|-------------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Recommended | Electrical Distribution | Replace |  | 1970 System | Capital | \$1,376,103 |



Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Site Only | | | | | | | |
|-------------------------------|-------------|----------------------------------|------------|---|-------------|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Recommended | Site Development | Replace |  | 1970 System | Capital | \$763,801 |
| 2015 | Recommended | Parking Lots | Replace |  | 1970 System | Capital | \$742,251 |
| 2015 | Recommended | Site Communications and Security | Replace |  | 1970 System | Capital | \$416,618 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Site Only | | | | | | | |
|-------------------------------|-------------|-------------------|------------|---|-------------|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2015 | Recommended | Site Lighting | Replace |  | 1970 System | Capital | \$290,370 |
| 2015 | Recommended | Landscaping | Replace |  | 1970 System | Capital | \$82,279 |
| 2020 | Recommended | Pedestrian Paving | Replace |  | 1970 System | Capital | \$524,118 |

Facility # 000008 Office. City Operations Building. COB. Downtown

| DEFICIENCY REPORT – Site Only | | | | | | | |
|-------------------------------|-------------|----------------|------------|--|-------------|--------------|-----------|
| Year | Priority | Subsystem | Correction | Photo | Location | Funding Type | Cost |
| 2020 | Recommended | Sanitary Sewer | Replace |  | 1970 System | Capital | \$384,193 |
| 2020 | Recommended | Water Supply | Replace |  | 1970 System | Capital | \$164,654 |

BORREGO SOLAR – FACILITY SOLAR ASSESSMENT: TRIP IV


Site Name: Development Review Center

Criteria 1: Facility is connected to the same meter as the City Administration Building


The proposed system to be installed on the roofs of the City Administration Building, San Diego Concourse Building, Civic Theater, and Development Review Center as well as on top of the Concourse Parkade parking structure. These buildings are connected to the same electrical system of the City Administration Building and have the physical space collectively to support larger arrays but this may be impractical because of the multiple shading impacts coming from the surrounding buildings. Please refer to the City Administration Building report for survey results and recommended system design for this building.

Clarification: In assessing the feasibility of installing a solar power system, a survey is conducted to investigate the condition and location of the existing electrical meter, switchgear, and transformer. The survey process also includes determining the most ideal location of where the solar modules would be installed and how it would connect to the existing electrical system. After the survey is conducted, a preliminary design phase incorporates all the findings from the survey as well as a full analysis on the recommended system size based on the electrical utility usage. This method ensures the most cost-effective solution for a site with multiple buildings. In this case, the system will be installed on the roofs of the City Administration Building, San Diego Concourse Building, Civic Theater, and Development Review Center as well as on top of the Concourse Parkade parking structure.

CITY OF SAN DIEGO SOLAR ASSESSMENT - PV PROJECT



PROJECT INFORMATION



THIS DOCUMENT IS PROVIDED BY BORREGO SOLAR SYSTEMS, INC. TO FACILITATE THE SALE AND INSTALLATION OF A SOLAR POWER SYSTEM FROM BORREGO SOLAR SYSTEMS. THIS IS A PRELIMINARY LAYOUT BASED ON AERIAL IMAGERY. THE ACTUAL PARAMETERS OF THE SYSTEM MAY VARY BASED ON A SITE SPECIFIC SURVEY AND THE COMPLETION OF DUE DILIGENCE EFFORTS. THESE DRAWINGS ARE NOT FOR CONSTRUCTION, REPRODUCTION, RELEASE OR UTILIZATION FOR ANY OTHER PURPOSE. WITHOUT PRIOR WRITTEN CONSENT IS STRICTLY PROHIBITED.





5005 TEXAS STREET, SUITE 400
SAN DIEGO, CA 92108
PHONE: (888) 898-6273
FAX: (888) 843-6778
WWW.BORREGOSOLAR.COM

PROPOSAL SPECIFICATIONS

| | | |
|---------------------------|--|------------------------|
| SYSTEM SIZE DC (KW) | 1,367,300 | |
| SYSTEM SIZE AC (KW) | 1100 | |
| DC TO AC RATIO | 1.24 | |
| MODULE INFORMATION | (4,972) LG 275 | |
| STRING INFORMATION | (226) PARALLELED STRINGS OF (22) | |
| INVERTER INFORMATION | (2) SMA SC500CP-US | |
| INTERCONNECTION VOLTAGE | TBD | |
| TRANSFORMER | NONE | |
| RACKING DETAILS | ROOF MOUNTED SUNLINK CORE & SOLAR SUPPORT STRUCTURES | |
| ARRAY PITCH (METER) | 1.98 | 32.71 N |
| ASCE7-05 WIND SPEED (MPH) | 85 | GROUND SNOW LOAD (PSF) |
| | | 0 |

ARRAY INFORMATION

| ARRAY NO. | AZIMUTH | TILT ANGLE | NO. OF MODULES | NO. OF STRINGS | KW DC | INVERTER CONNECTED |
|-----------|---------|------------|----------------|----------------|----------|--------------------|
| ROOF-1 | 180° | 5° | 3718 | 169 | 1022,450 | |
| SS-1 | 180° | 7.5° | 638 | 29 | 175,450 | (2) 500CP |
| SS-2 | 270° | 7.5° | 616 | 28 | 169,400 | |
| TOTAL | - | - | 4,972 | 226 | 1367,300 | - |



CITY OF SAN DIEGO SOLAR ASSESSMENT
202 C ST,
SAN DIEGO, CA 92101

PROJECT NUMBER:
P-SD-005641

| REV | DATE | DRAWN | CHECKED | RELEASE LEVEL |
|-----|----------|-------|---------|-----------------|
| 1 | 08/11/14 | RX | JZ | PROPOSAL LAYOUT |

SCALE: 1"=10'
VALID ONLY WHEN PLOTTED
ANSI FULL BLEED 8 1/2" X 11"

PV-1

L1 PROPOSAL LAYOUT